Annual Compliance Report 2024

20 February 2024

Bago Forest Quarry

(Formerly called Herons Creek Quarry)
31 Lookout Road, Herons Creek
Lot 161, Part Lot 52 and Part Lot 53 DP 754445 and Crown Land
also known as Compartments 42 & 43 of Broken Bago State Forest
(comprising an area of 188 ha.)

Approval authority: Joint Regional Planning Panel

(via Port Macquarie-Hastings Council)

Reference for this Report DA 2015/953 Condition F (17)

Development Application

Number: DA 2015/953
Date of Notification of Consent: 20 February 2017
Modification to Consent: 18 September 2019
Further Modification of Consent: 21 November 2023

Original Determining Authority: Joint Regional Planning Panel (JRPP) 2023 Determining Authority: Port Macquarie-Hastings Council

Applicant CTK Natural Resources Pty Ltd

Tenure

Type Forest Materials Licence
Licensor Forestry Corporation of NSW
Licensee CTK Natural Resources Pty Ltd

Licence Terms: Quarrying & associated works: 20 years. Limitations on tenure Licensor retains the right to harvest trees.

Compliance with Development Consent

(A) General Matters All relevant conditions have been

complied with.

(B) Prior to Issue of Construction Cert. All relevant conditions have been

complied with.

(C) Construction Certificates All relevant conditions have been

complied with.

(D) During Work

All relevant conditions have been

complied with.

(E) Prior to Issue of Occupation Certificate.

All requirements have been satisfied. The Occupation Certificate was issued by

Council on 15 February 2022.

(F) Occupation of the Site

The 20 conditions in this section of the Development Consent continue to be

complied with. Summary details are as follows:

1 On-site car parking is always available 2 All loading operations are being carried out within the confines of the site 3 All fire safety measures are always maintained 4 An annual fire safety statement has been provided to Council and the Commissioner 5 Material stockpiles are being managed to prevent wind-blown dust 6 Liquid materials are being stored in roofed and impervious bund areas 7 Contaminated run-off is prevented from entering the stormwater system 8 Offensive noise is not being generated 9 Greenhouse gas reduction strategies are being implemented as per EIS assessment 10 There has been no breach of water quality standards (specified in the EPL) during the year 11 Extraction from stage 4 has not started. This condition will be addressed in due course. 12 Rehabilitation has not yet commenced. A monitoring plan will be provided to Council in due course 13 This condition was deleted in the 2023 Modification of Consent. 14 Haulage truck drivers continue to be advised to travel south along Bago Road whenever possible. 15 Milligan's Road access is only being used for emergencies. The gate at Trail 43/2 remains locked. 16 All material exported from site is being recorded at the weighbridge 17 Compliance reports continue to be submitted to Council annually. 18 Hours of quarry operation are being limited to 7 AM to 5 PM weekdays, and 7 AM to 1 PM Saturday 19 Blasting is being limited to periods between 10 AM and 3 PM 20 Recovered sediment is being transferred to overburden stockpile areas.	5	
All fire safety measures are always maintained An annual fire safety statement has been provided to Council and the Commissioner Material stockpiles are being managed to prevent wind-blown dust Liquid materials are being stored in roofed and impervious bund areas Contaminated run-off is prevented from entering the stormwater system Offensive noise is not being generated Greenhouse gas reduction strategies are being implemented as per EIS assessment There has been no breach of water quality standards (specified in the EPL) during the year Extraction from stage 4 has not started. This condition will be addressed in due course. Rehabilitation has not yet commenced. A monitoring plan will be provided to Council in due course This condition was deleted in the 2023 Modification of Consent. Haulage truck drivers continue to be advised to travel south along Bago Road whenever possible. Milligan's Road access is only being used for emergencies. The gate at Trail 43/2 remains locked. All material exported from site is being recorded at the weighbridge Compliance reports continue to be submitted to Council annually. Hours of quarry operation are being limited to 7 AM to 5 PM weekdays, and 7 AM to 1 PM Saturday Blasting is being limited to periods between 10 AM and 3 PM	1	On-site car parking is always available
An annual fire safety statement has been provided to Council and the Commissioner Material stockpiles are being managed to prevent wind-blown dust Liquid materials are being stored in roofed and impervious bund areas Contaminated run-off is prevented from entering the stormwater system Offensive noise is not being generated Greenhouse gas reduction strategies are being implemented as per EIS assessment There has been no breach of water quality standards (specified in the EPL) during the year Extraction from stage 4 has not started. This condition will be addressed in due course. Rehabilitation has not yet commenced. A monitoring plan will be provided to Council in due course This condition was deleted in the 2023 Modification of Consent. Haulage truck drivers continue to be advised to travel south along Bago Road whenever possible. Milligan's Road access is only being used for emergencies. The gate at Trail 43/2 remains locked. All material exported from site is being recorded at the weighbridge Compliance reports continue to be submitted to Council annually. Hours of quarry operation are being limited to 7 AM to 5 PM weekdays, and 7 AM to 1 PM Saturday Blasting is being limited to periods between 10 AM and 3 PM	2	All loading operations are being carried out within the confines of the site
Material stockpiles are being managed to prevent wind-blown dust Liquid materials are being stored in roofed and impervious bund areas Contaminated run-off is prevented from entering the stormwater system Offensive noise is not being generated Greenhouse gas reduction strategies are being implemented as per EIS assessment There has been no breach of water quality standards (specified in the EPL) during the year Extraction from stage 4 has not started. This condition will be addressed in due course. Rehabilitation has not yet commenced. A monitoring plan will be provided to Council in due course This condition was deleted in the 2023 Modification of Consent. Haulage truck drivers continue to be advised to travel south along Bago Road whenever possible. Milligan's Road access is only being used for emergencies. The gate at Trail 43/2 remains locked. All material exported from site is being recorded at the weighbridge Compliance reports continue to be submitted to Council annually. Hours of quarry operation are being limited to 7 AM to 5 PM weekdays, and 7 AM to 1 PM Saturday Blasting is being limited to periods between 10 AM and 3 PM	3	All fire safety measures are always maintained
6 Liquid materials are being stored in roofed and impervious bund areas 7 Contaminated run-off is prevented from entering the stormwater system 8 Offensive noise is not being generated 9 Greenhouse gas reduction strategies are being implemented as per EIS assessment 10 There has been no breach of water quality standards (specified in the EPL) during the year 11 Extraction from stage 4 has not started. This condition will be addressed in due course. 12 Rehabilitation has not yet commenced. A monitoring plan will be provided to Council in due course 13 This condition was deleted in the 2023 Modification of Consent. 14 Haulage truck drivers continue to be advised to travel south along Bago Road whenever possible. 15 Milligan's Road access is only being used for emergencies. The gate at Trail 43/2 remains locked. 16 All material exported from site is being recorded at the weighbridge 17 Compliance reports continue to be submitted to Council annually. 18 Hours of quarry operation are being limited to 7 AM to 5 PM weekdays, and 7 AM to 1 PM Saturday 19 Blasting is being limited to periods between 10 AM and 3 PM	4	An annual fire safety statement has been provided to Council and the Commissioner
7 Contaminated run-off is prevented from entering the stormwater system 8 Offensive noise is not being generated 9 Greenhouse gas reduction strategies are being implemented as per EIS assessment 10 There has been no breach of water quality standards (specified in the EPL) during the year 11 Extraction from stage 4 has not started. This condition will be addressed in due course. 12 Rehabilitation has not yet commenced. A monitoring plan will be provided to Council in due course 13 This condition was deleted in the 2023 Modification of Consent. 14 Haulage truck drivers continue to be advised to travel south along Bago Road whenever possible. 15 Milligan's Road access is only being used for emergencies. The gate at Trail 43/2 remains locked. 16 All material exported from site is being recorded at the weighbridge 17 Compliance reports continue to be submitted to Council annually. 18 Hours of quarry operation are being limited to 7 AM to 5 PM weekdays, and 7 AM to 1 PM Saturday 19 Blasting is being limited to periods between 10 AM and 3 PM	5	Material stockpiles are being managed to prevent wind-blown dust
9 Greenhouse gas reduction strategies are being implemented as per EIS assessment 10 There has been no breach of water quality standards (specified in the EPL) during the year 11 Extraction from stage 4 has not started. This condition will be addressed in due course. 12 Rehabilitation has not yet commenced. A monitoring plan will be provided to Council in due course 13 This condition was deleted in the 2023 Modification of Consent. 14 Haulage truck drivers continue to be advised to travel south along Bago Road whenever possible. 15 Milligan's Road access is only being used for emergencies. The gate at Trail 43/2 remains locked. 16 All material exported from site is being recorded at the weighbridge 17 Compliance reports continue to be submitted to Council annually. 18 Hours of quarry operation are being limited to 7 AM to 5 PM weekdays, and 7 AM to 1 PM Saturday 19 Blasting is being limited to periods between 10 AM and 3 PM	6	Liquid materials are being stored in roofed and impervious bund areas
9 Greenhouse gas reduction strategies are being implemented as per EIS assessment 10 There has been no breach of water quality standards (specified in the EPL) during the year 11 Extraction from stage 4 has not started. This condition will be addressed in due course. 12 Rehabilitation has not yet commenced. A monitoring plan will be provided to Council in due course 13 This condition was deleted in the 2023 Modification of Consent. 14 Haulage truck drivers continue to be advised to travel south along Bago Road whenever possible. 15 Milligan's Road access is only being used for emergencies. The gate at Trail 43/2 remains locked. 16 All material exported from site is being recorded at the weighbridge 17 Compliance reports continue to be submitted to Council annually. 18 Hours of quarry operation are being limited to 7 AM to 5 PM weekdays, and 7 AM to 1 PM Saturday 19 Blasting is being limited to periods between 10 AM and 3 PM	7	Contaminated run-off is prevented from entering the stormwater system
There has been no breach of water quality standards (specified in the EPL) during the year Extraction from stage 4 has not started. This condition will be addressed in due course. Rehabilitation has not yet commenced. A monitoring plan will be provided to Council in due course This condition was deleted in the 2023 Modification of Consent. Haulage truck drivers continue to be advised to travel south along Bago Road whenever possible. Milligan's Road access is only being used for emergencies. The gate at Trail 43/2 remains locked. All material exported from site is being recorded at the weighbridge Compliance reports continue to be submitted to Council annually. Hours of quarry operation are being limited to 7 AM to 5 PM weekdays, and 7 AM to 1 PM Saturday Blasting is being limited to periods between 10 AM and 3 PM	8	Offensive noise is not being generated
Extraction from stage 4 has not started. This condition will be addressed in due course. Rehabilitation has not yet commenced. A monitoring plan will be provided to Council in due course This condition was deleted in the 2023 Modification of Consent. Haulage truck drivers continue to be advised to travel south along Bago Road whenever possible. Milligan's Road access is only being used for emergencies. The gate at Trail 43/2 remains locked. All material exported from site is being recorded at the weighbridge Compliance reports continue to be submitted to Council annually. Hours of quarry operation are being limited to 7 AM to 5 PM weekdays, and 7 AM to 1 PM Saturday Blasting is being limited to periods between 10 AM and 3 PM	9	Greenhouse gas reduction strategies are being implemented as per EIS assessment
12 Rehabilitation has not yet commenced. A monitoring plan will be provided to Council in due course 13 This condition was deleted in the 2023 Modification of Consent. 14 Haulage truck drivers continue to be advised to travel south along Bago Road whenever possible. 15 Milligan's Road access is only being used for emergencies. The gate at Trail 43/2 remains locked. 16 All material exported from site is being recorded at the weighbridge 17 Compliance reports continue to be submitted to Council annually. 18 Hours of quarry operation are being limited to 7 AM to 5 PM weekdays, and 7 AM to 1 PM Saturday 19 Blasting is being limited to periods between 10 AM and 3 PM	10	There has been no breach of water quality standards (specified in the EPL) during the year
This condition was deleted in the 2023 Modification of Consent. Haulage truck drivers continue to be advised to travel south along Bago Road whenever possible. Milligan's Road access is only being used for emergencies. The gate at Trail 43/2 remains locked. All material exported from site is being recorded at the weighbridge Compliance reports continue to be submitted to Council annually. Hours of quarry operation are being limited to 7 AM to 5 PM weekdays, and 7 AM to 1 PM Saturday Blasting is being limited to periods between 10 AM and 3 PM	11	Extraction from stage 4 has not started. This condition will be addressed in due course.
Haulage truck drivers continue to be advised to travel south along Bago Road whenever possible. Milligan's Road access is only being used for emergencies. The gate at Trail 43/2 remains locked. All material exported from site is being recorded at the weighbridge Compliance reports continue to be submitted to Council annually. Hours of quarry operation are being limited to 7 AM to 5 PM weekdays, and 7 AM to 1 PM Saturday Blasting is being limited to periods between 10 AM and 3 PM	12	Rehabilitation has not yet commenced. A monitoring plan will be provided to Council in due course
Milligan's Road access is only being used for emergencies. The gate at Trail 43/2 remains locked. All material exported from site is being recorded at the weighbridge Compliance reports continue to be submitted to Council annually. Hours of quarry operation are being limited to 7 AM to 5 PM weekdays, and 7 AM to 1 PM Saturday Blasting is being limited to periods between 10 AM and 3 PM	13	This condition was deleted in the 2023 Modification of Consent.
All material exported from site is being recorded at the weighbridge Compliance reports continue to be submitted to Council annually. Hours of quarry operation are being limited to 7 AM to 5 PM weekdays, and 7 AM to 1 PM Saturday Blasting is being limited to periods between 10 AM and 3 PM	14	Haulage truck drivers continue to be advised to travel south along Bago Road whenever possible.
Compliance reports continue to be submitted to Council annually. Hours of quarry operation are being limited to 7 AM to 5 PM weekdays, and 7 AM to 1 PM Saturday Blasting is being limited to periods between 10 AM and 3 PM	15	Milligan's Road access is only being used for emergencies. The gate at Trail 43/2 remains locked.
Hours of quarry operation are being limited to 7 AM to 5 PM weekdays, and 7 AM to 1 PM Saturday Blasting is being limited to periods between 10 AM and 3 PM	16	All material exported from site is being recorded at the weighbridge
19 Blasting is being limited to periods between 10 AM and 3 PM	17	Compliance reports continue to be submitted to Council annually.
	18	Hours of quarry operation are being limited to 7 AM to 5 PM weekdays, and 7 AM to 1 PM Saturday
20 Recovered sediment is being transferred to overburden stockpile areas.	19	Blasting is being limited to periods between 10 AM and 3 PM
	20	Recovered sediment is being transferred to overburden stockpile areas.

Section 138 Roads Act:

Approval issued with CC 17.2015.0953.02. Certificate of Completion issued by Council on 11 February 2022.

2

Section 68 Local Government Act: Approval Issued 24 January 2018

Application No: 680.2015.00000953.002

Environment Protection Licence

Issuing Authority EPA Licence No: 20983

Issue Date: 26 October 2018

Anniversary Date 26 October. The licence has recently been

varied.

Scheduled activities: Extractive Activities

Crushing, Grinding or Separating

Quarry OperationsBago Forest Quarry commenced business

operations on 1 March 2022

Graham Lockett

Managing Director CTK Natural Resources Pty Ltd

3